DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/Ala Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-015336 Address: 333 Burma Road **Date Inspected:** 30-Jun-2010

City: Oakland, CA 94607

Project Name: SAS Superstructure OSM Arrival Time: 1900 **OSM Departure Time:** 700 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: See below **CWI Present:** Yes No Yes N/A **Rod Oven in Use:** Yes No **Inspected CWI report:** No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component:** Tower and OBG Components

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance Inspector (QA Inspector) George Goulet was present during the times noted above for observations relative to the work being performed.

Bay 10

This QA Inspector randomly observed no welding related work in progress in Bay 10.

Bay 11

This QA Inspector randomly observed no welding related work being performed in Bay 11.

Heavy Dock

This QA Inspector randomly observed the following work being performed on the Heavy Dock:

This QA Inspector observed no welding related work was being performed on the heavy dock. All 4 tower lifts 2 were erect with all 4 tower lifts 3 attached above, respectively. Crossbeam 7 and crossbeam 8 were sitting on stanchions on the foot of the dock. ZPMC workers were bolting splice plates under the deck plates for apparent safekeeping during shipping. No ZPMC floating crane was in the immediate area. The worker access tower elevator was dark.

OBG Trial Assembly Area

This QA Inspector randomly observed the following work in progress in the OBG Trial Assembly Area:

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

SMAW welding of weld joint RETRO-G-01-8CW-A1-033, 034 located inside the OBG at PCMK 8CW, retrofit plates to side plates south (crossbeam) side. Welder was identified as 059450. QC was identified as ZPMC CWI Wu Zhi Cheng (QC1). Assisting QC1 at this location and appearing to be monitoring the welding and recording data was ZPMC QC Xu Jin Long, who was not a CWI. Welding variables recorded by QC1's assistant appeared to comply with WPS-B-P-2113-FCM-1 as presented to this QA Inspector.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No significant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, 150-0042-2372, who represents the Office of Structural Materials for your project.

Inspected By:	Goulet,George	Quality Assurance Inspector
Reviewed By:	Dawson,Paul	QA Reviewer